



### **Description**:

RBCuZn-C, commonly called LFB Bare or Coated is a general purpose oxyacetylene/brazing rod used for joining various ferrous and nonferrous metals such as carbon steel, copper alloys, cast iron, malleable iron, stainless steel, and some nickel alloys. A must in every welding shop is XTRweld Low Fuming Bronze)

## **Typical Applications:**

XTR LFB Low furning bronze (bare and flux coated) is a general-purpose, copper base alloy brazing rod used extensively for gas brazing steel, copper alloys, cast iron, nickel alloys and stainless steel. Its low fuming characteristic and good mechanical properties make this alloy a widely used general-purpose product. Preheating is recommended for some applications and a bronze brazing flux is required if the rod is not coated. This brazing rod has a low melting point making it easily machinable and excellent for sheet metal work. This alloy also possesses high tensile strength and good ductility.

If using flux coated product (White), there is no need for additional flux. When using the bare (non-Coated) product, be sure to use a borax-boric acid flux.

### Chemistry:

Typical	AWS Spec. Single values are max.
59.550	56.0-60.0
38.784	Bal.
0.985	0.80-1.10
0.435	0.25-1.20
0.120	0.01-0.50
0.004	0.050
0.002	0.010
0.120	0.04-0.15
	<b>Typical</b> 59.550 38.784 0.985 0.435 0.120 0.004 0.002 0.120



#### Mechanical Properties: (As Welded)

	Typical
Tensile Strength	60-68k psi
Yield Strength	64,000 psi
Melting Point	1,630°F
Solidification	1,590°F
Brazing Range	1,330-1,550°F
Brinell Hardness	80-105 Brinell
Color	Yellow Brass

# Welding Positions:

H. V

### **Recommended Procedures:**

- 1. Bevel cracks or heavy sections. Be sure to clean all areas to be joined or built-up thoroughly
- 2. Joint clearances should not exceed 0.13mm
- 3. Using a slightly oxidizing flame, preheat the part to be brazed. If using LFB Bare, dip the rod into the bronze brazing flux (no need for more flux if using XTR LFB Coated Rods) and then back to the area being brazed, while keeping the torch in continuous motion to avoid any overheating. Molten drops of LFB will follow the heat of the torch flame

AWS Spec. Single values are min. ns ns

- 4. When using flux coated LFB, there is generally no need clean flux residue between passes
- 5. Allow the part to cool slowly before removing any slag, then use a wire brush to clear
- 6. Repeat as necessary to fill your joint



#### www.XTRweld.com

Ver. 10.1.2021 XTRweld and Alliance Distribution Partners believes that all of the information and technical data given is correct. This information is given to assist in making your own evaluations and/or decisions, this should not be mistaken as an expressed or implied warranty. XTRweld assumes no liability for results or damages incurred from the use of any information contained in this document in part or in whole. Material is free from mercury and radioactive contamination